

European Washing Symbols

Lavagem



Machine wash at 95°C or less.



Machine wash at 60°C or less.



Machine wash at 60°C or less on reduced cycle.



Machine wash at 50°C or less on reduced cycle.



Machine wash at 40°C or less.



Machine wash at 40°C or less on reduced cycle.



Machine wash on gentle cycle at 40°C or less.



Machine wash at 30°C or less.



Machine wash at 30°C or less on reduced cycle.



Machine wash on gentle cycle at 30°C or less.



Hand wash only



Do not wash.

Lixívia



Chlorine bleach allowed in cold and diluted solution.



Do not use chlorine bleach.

Secagem

















Dry flat.



Hang Dry.



Drip

	May be tumble dried, no restrictions.
	Tumble dry at low setting.
	Tumble dry at high setting.
	Do not tumble dry.
Passar a ferro	
	Iron at maximum temperature of 110°C.
	Iron at maximum temperature of 150°C.
	Iron at maximum temperature of 200°C.
	Do not iron
Limpeza a seco	
	May be dry cleaned in any type of solvent normally used in dry cleaning processes.
	May be dry cleaned in any type of solvent normally used in dry cleaning processes except trichloroethylene.
	Limitations are placed on the addition of water/mechanical action or temperature during normal dry cleaning process.
	Only petroleum solvents may be used
	Limitations are placed on the addition of water/mechanical action or temperature during normal dry cleaning process..
	Do not dry clean.